

Sheet1

ROCKWELL 500S SHRIKE COMMANDER

3050	N9038N	<u>ACCIDENT 250621, STILL CURRENT 130322</u>	
3051	N9039N	N847	N847T
	N811PJ		
3052	(N9072N)	AN-ASD	AN-BIH
3053	N9026N	VH-EXE	VH-YJE
3054	N9005N	C-GSJK	N9005N
	VH-WGY	N9005N	
3055	N9072N	VH-PWO	(CF-)
	N10022	VH-PWO	VH-UJU
<u>CNX 180706, NON COMPLIANCE WITH REGULATIONS</u>			
3056	N9008N	N900DT	(N901JF)
	N900DT	<u>DEST 280820, CNX 240321</u>	
3057	N9021N	(N274HL)	N9021N
	VH-IBY	VH-TFY	<u>WFU, CNX 140313</u>
3058	N326MB	N326JR	<u>SUBS DAM 080686, CNX 110309</u>
3059	N9027N	N531SA	
3060	N9034N	VH-IBV	VH-YJP
	VH-WZU	VH-WZE	<u>WO 240211, CNX 201016</u>
3061	N9062N	HK-1209/P	
3062	N9075N	OH-ACC	SE-ERH
	N2973F		
3063	N9076N	<u>WO 230595, CNX 080813</u>	
3064	N9077N	(N907CC)	N9077N
	<u>XB-YOH CNX BY 0987</u>		
3065	N9078N	XB-APD	XB-SUB
	XA-CAD	N7259	N40AW
	N45DH	N900CH	N8LX
3066	N9080N	TG-JOT	<u>WO 050975</u>
3067	N9081N	N88CB	<u>WO 151106, CNX 080115</u>
3068	N9082N	<u>CR 230994, CNX 020413</u>	
3069	N9083N	VH-EXS	<u>WFU, CNX 020409</u>
3070	N9084N	D-IDSS	N900RA
<u>CR 211101, CNX 211101</u>			
3071	N9085N	N45WS	VH-ZZS
	<u>VH-FGZ CNX 301121</u>		
3072	N9093N	<u>WO 191269, CNX 160670</u>	
3073	N9094N	N98TT	<u>DBR 250502, SPARES, CNX 100513</u>
3074	N9095N	VH-EXO	VH-UJP
<u>CR 121295</u>			
3075	PP-SEB	<u>CNX BY 0287</u>	
3076	N9096N		
3077	N9098N	YV-1550P	
3078	N9099N	N90JP	
3079	(N9100N)	N1007S	CS-AJV
	D2-		
3080	(N9103N)	N5018E	OB-1665
	N717MP	VH-TZS	
3081	N9104N	N222GS	N519WA
3082	N9106N	N77VF	N5800H
<u>DBR 180710, CNX 280111</u>			
3083	N9112N	N500DJ	OB-1666
	N58CR	HP-	
3084	N9113N	<u>REGN EXPD, CNX 040217</u>	

Sheet1

3085	N9114N N47SC N260AC <u>DBR 140791, CNX 070417</u>	TG-BEG N260AC	N11KC (ZK-ESO)
3086	N9116N (N91BK)	(N913AC) N9116N	N9116N VH-XAS
3087	N9119N	<u>WO 011070, CNX 180271</u>	
3088	N9120N	VH-UJL	
3089	N9122N	VH-FGT	VH-YJT
	<u>WO 211098, CNX 060999</u>		
3090	(N9123N)	EP-PAB	
3091	(N9125N)	OH-ACD	SE-EWH
	N40TC <u>WO 170514, CNX 090115</u>		
3092	(N9126N) (N57033)	N3007H N303E	N303E
3093	N9128N	<u>WO 121071, CNX 301171</u>	
3094	(N9131N)	PP-SEC	<u>WO 150307</u>
3095	(N9132N) N717AM TG-RPM	D-IDAO N611FA	N67270 N926CM
3096	(N9133N) N39GW	N49NP	C6-BEP
3097	N9134N	N411JT	<u>WO 240608, CNX 050515</u>
3098	(N9135N) HR-AKM	TG-JUT	TG-CNA
3099	(N9136N) N38GW	N59NP N571DC	C6-BDF
3100	N9139N	N69NP	<u>WO 260973, CNX 181273</u>
3101	(N9140N)	N201FE	6Y-JHV
	<u>WO 280286, CNX 170492</u>		
3102	(N9141N)	PT-DRO	
3103	(N9145N) N29NP C-FMUM	N10WS C6-BEM	N16WS N37GW
3104	(N9147N) PT-KXV	PP-FRA	PT-FRA
3105	(N9148N)	PP-FRB	PT-FRB
	PT-KZU <u>WFU, CNX 310190</u>		
3106	(N9150N)	ZP-TFV	
3107	(N9151N)	TG-JUO	
3108	N9152N N129MB	N510EC	N129ME
3109	(N9155N)	HK-1208	<u>WO 181272</u>
3110	(N9156N)	PT-IAT	
3111	N9157N	VH-LST	<u>WO 190204, CNX 230304</u>
3112	N9158N	AN-MDN	YN-MDN
3113	N9159N	PT-ICR	
3114	N9160N	PT-ICS	
3115	N9167N	N86SS	N680SS
	<u>REGN EXPD, CNX 290714</u>		
3116	(N9168N)	PT-IKX	<u>CNX BY 0287</u>
3117	(N9169N)	N5007H	VH-UJM
	<u>WFU 0615, CNX 121015</u>		
3118	N9170N	C-GAYR	C-FRBD
3119	N9171N	<u>DBR 141092, CNX 130295</u>	
3120	N9172N (D-ICKT)	(HB-GFD) N9172N	N9172N CR-AOU

Sheet1

	(C9-AOU)	(G-BEWE)	"VP-WGQ"
	ZS-KBF	N106WE	N500BA
	VH-BGE	(VH-YJO)	VH-UJE
3121	N9173N	N803AC	HI-624CT
	N803AC	N634CT	
3122	N9174N	CF-JAJ	N214JA
3123	N9178N	8P-ECT	N8042G
	N500MT	TG-JAD	
3124	N9176N	CR-AOA	C9-AOA
3125	N9177N	N9177	
3126	N9179N	(N38MB)	N4XR
	N915PR	XA-	N915PR
3127	(N9180N)	N500RA	<u>REGN EXPD, CNX 190313</u>
	<u>PVD STEVEN UDVAR-HAZY CENTER, CHANTILLY, VA</u>		
3128	(N9180N)	N777DT	N207JG
3129	PT-IGL		
3130	N9182N	VH-BAJ	VH-YJI
3131	N9186N		
3132	N9184N	ZS-IZN	
3133	(N9185N)	YV-TABM	YV-704P
	N500VE		
3134	N9183N	N402ST	(N412ST)
	N402SD	(N345RJ)	N402SD
	CC-CKK	YV-908P	
3135	N9103N	CR-AOB	C9-AOB
3136	N9105N	CR-AOC	<u>CR 250374</u>
3137	N9118N	CR-AOD	C9-AOD
	(G-BETK)	N9118N	ZK-PAT
	VH-WAM		
3138	(N9123N)	N1BK	N535SA
	N760VR		
3139	N9189N	CR-AOG	C9-AOG
	<u>DLICT BY 100896</u>		
3140	N9190N	CR-AQB	C9-AQB
	9Q-CTJ	G-BEZN	(N9190N)
	N500BL	PT-KZD	<u>WO 020702</u>
3141	502 (IRAN NAV)	5-2502	
3142	503	5-2503	
3143	504	5-2504	
3144	(N9187N)	D-ICKT	N3234G
	N914AC	C-FJPW	N725AC
	<u>CR 070292, CNX 070695</u>		
3145	N9188N	N202JH	
3146	N9141N	N3U	N3UX
	N3U	N3UV	
3147	6Y-JHY		
3148	N9163N	6Y-JIB	N9163N
	N766WC	N768WC	CC-CAE
	CC-PXE		
3149	N9180N	JA5200	N500SJ
3150	(N9181N)	PT-IQG	<u>WO 300875</u>
3151	N9143N	5B-CFE	(N163AP)
	5B-CFE	V5-CFE	ZS-NRO
	VH-UJN		
3152	N5036E	VH-EXJ	VH-UJB
	<u>WO 100401, CNX 300501</u>		

Sheet1

3153	N9224N	CS-AOI	<u>DEST 210586</u>
3154	(N9193N)	YS-130P	N8520K
3155	N6520V	N500HM	
3156	TG-JAC		
3157	N9236N	VH-EXH	<u>DEST, CNX 0888</u>
3158	N9244N	G-BBLI	N801AC
	(N50BK)	N801AC	VH-MDW
3159	(TG-JAC)	(N9164N)	PT-IZX
3160	N9198N	N19WL	<u>CR 140403, CNX 081004</u>
3161	N57024	N712PC	VH-UJV
3162	(N9197N)	(N10LE)	N20LE
	N73U	<u>WO 250509, CNX 110809</u>	
3163	(N57030)	HK-1490/W	
3164	N447V	VH-KAV	
3165	N57038	PT-JKI	
3166	N57039	PT-JLX	
3167	(N8007H)	N57040	N193SS
	N1938S		
3168	(N57042)	8P-HPT	<u>DLICT</u>
3169	(N57043)	N54LW	N536SA
3170	N57046	VH-TSS	VH-UJY
3171	N57055	8P-EWT	(N57055)
	<u>DLICT</u>		
3172	N57062	LV-CVI	
3173	N57239	N32MH	N32NH
	N707WM	N272BB	<u>WO 06001, CNX 060317</u>
3174	(N57063)	TG-LEM	N1015E
	VH-TOL	<u>CR 081181</u>	
3175	(N57076)	PT-JNK	N975AA
3176	N57029	VH-ACZ	VH-YJC
3177	N57078	CS-APZ	SE-LCN
3178	N57079	VH-ACJ	VH-YJJ
3179	N57082	CR-AOO	C9-AOO
	<u>CR 170588</u>		
3180	N57083	G-BCLK	N1187G
	N101AA	<u>WO 020714, CNX 160318</u>	
3181	YV-TAHN	YV-57CP	YV-570P
	YV-04CP	N65375	PR-BJP
3182	(N57090)	N241PJ	N444TS
3183	N57241	XC-GOZ	N106TW
3184	N57084	(N574D)	N57084
3185	N57242	VH-KAC	<u>WFU, CNX 020409</u>
3186	(N57252)	RP-C1268	VH-YJM
3187	PT-KBF	HK-4577	
3188	N57243	N5B	N500WW
	VH-SDI	<u>DEST, CNX 200588</u>	
3189	N57244	CR-AQM	C9-AQM
3190	PT-KDF		
3191	N57245	N12MU	N741CA
3192	(N57251)	N812PS	N812BS
	N500LF	<u>REGN EXPD, CNX 100513</u>	
3193	YV-TAKM	YV-824P	N4558W
	<u>WO 110892, CNX 171214</u>		
3194	EP-AHS		
3195	YV-TOWV	YV-313P	YV1158

Sheet1

3196	EP-AHT <u>WFU, SCR 0611</u>		
3197	N57257	CR-ARB	C9-ARB
3198	HK-1697G/-P		
3199	CP-1126	HC-BHN	HK-4359X/-P
3200	N57274	G-BCPZ	N47AC
3201	CP-1127 <u>WO 270179</u>		
3202	(N57265)	N57276	ZS-JPO
	VH-JPO		
3203	N57278 <u>CR 181176, CNX 100177</u>		
3204	ET-AFN <u>DBR 011085, DLICT BY 12</u>		
3205	N57283	EP-AMO <u>WFU & CNX</u>	
3206	N57261	N57GB	(N600LB)
	N57GB	N79NU <u>CR 110296, CNX 191101</u>	
3207	5Y-AUF	N500RX	
3208	N57266		
3209	TG-JWC		
3210	N57272	EP-AMP	
3211	ETL-1251 (MEX AF)	5151	
3212	ETL-1252	5152	
3213	ETL-1253	5153	
3214	ETL-1254	5154	
3215	ETL-1255	5155	
3216	ETL-1256	5156	
3217	ETL-1257	5157	
3218	ETL-1258	5158	
3219	ETL-1259	5159	
3220	ETL-1260	5160	
3221	YV-TAKR	YV-827P <u>WO 270679</u>	
3222	5Y-AUO	5Y-BBP <u>WO 200784</u>	
3223	(N57116)	EP-AMG	
3224	N57284	LV-PTV	LV-LSL
	N101EJ	N501AP <u>WO 090608, CNX 291008</u>	
3225	EP-AMH		
3226	N57134	G-BDAL	VH-DZC
3227	N57150	N2BZ	
3228	N57247	LV-PUN	LV-LSA
	PP-JBE		
3229	OH-ACL	N99GC	OH-ACL
	<u>WFU, CNX 170899</u>		
3230	YV-TAKS	YV-183P	(C-GIIL)
	N567PT	CC-CFW	
3231	N57251	VH-PCO	VH-YJR
3232	(N57252)	LV-PTR	LV-LSE
	N775JB	N909AK <u>DEST 280520, STILL CURRENT 130322</u>	
3233	N57258	N973H	N66AV
	N97VB <u>WO 280205, CNX 150916</u>		
3234	N57260	N40MA	
3235	(N57263)	(N1264B)	N7764B
	N961SC		
3236	N57265	EP-AMQ	EP-MAA
	<u>DISM 0811</u>		
3237	YV-T-ARX	YV-968P	YV-2469P
3238	N57076	LV-PUO	LV-LSY
3239	N57262		
3240	ETL-1261 (MEX AF) <u>WO 111283</u>		

Sheet1

3241	ETL-1262	5162	
3242	ETL-1263	5163	
3243	ETL-1264	5164	
3244	ETL-1265	5165	
3245	ETL-1266	<u>PVD SANTA LUCIA</u>	
3246	ETL-1267	5167	
3247	ETL-1268	5168	
3248	ETL-1269	5169	
3249	ETL-1270	5170	
3250	(ETL-1266)	N31208	(ZP-PJU)
	N31208	CC-CKS	
3251	(ETL-1267)	N57162	VH-EXC
3252	(ETL-1268)	(N57163)	(YV-TAUD)
	YV-30P	YV1616	
3253	(ETL-1269)	N57167	N808AC
	J8-VBE	J8-KIM	
3254	(ETL-1270)	(N57196)	(YV-TAUE)
	YV-31P	YV-281C	YV-404CP
3255	(N57198)	N12RS	N280MB
3256	N57199	N407H	YV-81CP
	<u>CNX BY 0686</u>		
3257	N57209	ZS-JRG	VH-XWD
	VH-MLG		
3258	N57213	VH-MEH	(VH-YJH)
	VH-MEH		
3259	ZP-PKA	N25202	N917AC
	N42MS		
3260	N57222	VR-CAT	N57222
	VH-AUU	VH-WPY	VH-WRG
3261	N57225	N535E	N585E
	N500FC	N47RF	N9094X
	N47SC	N47RF	N578WY
3262	N57288	OB-1690	N507JP
3263	N57290	XC-BEL	N57290
	N105TW	VH-SDO	<u>DBR, CNX 0286</u>
3264	(N81405)	YV-572P	YV-2291P
	N70343	(CC-)	N70343
	VH-LET		
3265	N81391	N8139P	<u>CR 170985, CNX DATE?</u>
3266	(N57162)	N57130	ZS-JUN
	N682TC	ZS-DAW	
3267	N57117	N8536	
3268	(YV-391P)	N81440	HR-315
	HR-AFB		
3269	(N57213)	N57163	VH-KAK
3270	(YV-24P)	YV-29P	N2089R
	CC-CFN	CC-PFK	
3271	(N57267)	HR-317	HR-AFC
3272	N81459	ZS-JRS	N81459
	VH-NLL		
3273	(N81394)	YV-935P	YV-611CP
	(N6624L)	YV-611CP	
3274	N81397	N292S	
3275	N81450	C-GETJ	
3276	N81454		

Sheet1

3277	(N81458)	N9NR	N90CR	
	N999N	<u>CR 170202, CNX 100203</u>		
3278	N407H	C-GDAM	N49776	
	YV-1928P	YV-258C	YV-1007CP	
	YV1586			
3279	N81504	VH-EXY	VH-UJZ	
	<u>WO 171007, CNX 221008</u>			
3280	N81512	VH-MAV		
3281	N81514	ZS-JRT	N807AC	
	<u>REGN EXPD, CNX 260218</u>			
3282	N81515	YS-129P	TG-COM	
3283	<u>NOT BUILT</u>			
3284	<u>NOT BUILT</u>			
3285	<u>NOT BUILT</u>			
3286	<u>NOT BUILT</u>			
3287	<u>NOT BUILT</u>			
3288	<u>NOT BUILT</u>			
3289	<u>NOT BUILT</u>			
3290	N81522	N999DA		<i>CNX 100818, REST 191018</i>
3291	(N81538)	N12RS	N12RZ	
	CC-CKI	CC-PKB	HC-CIL	
3292	(N81552)	N2300H	N37MB	
	<u>STOLEN 140887, NOT RECOVERED, CNX 020595</u>			
3293	N81580	N916AC	CC-CHG	
	<u>CNX 100709</u>			
3294	N81581	YV-131CP	YV-1402P	
	N342LD	PT-WJM		
3295	(N81582)	YV-125CP	YV-1226P	
	N387DH	<u>REGN EXPD, CNX 130918</u>		
3296	N81587	N12LD	JA5313	
	VH-JAJ			
3297	N81589	<u>CR 251185, CNX DATE?</u>		
3298	(N81591)	N766WC	(N866WC)	
	N766WC	N766WC	N51RF	
	<u>WO 080411, CNX 141112</u>			
3299	N12RS	N109SA	(N101EC)	
	N80PG	N651CA	N811CR	
	(N811QR)	N811CR	N50BA	
	VH-YJB	<u>WO 310707, CNX 030807</u>		
3300	YV-1337P	N123HT		
3301	N81880	(ZP-PNP)	N81394	
	VH-TWS	VH-UJI		
3302	(N81882)	N35SA	N35HM	
	N35MB	N88XX	N903AK	
	<u>DAM 190303, CNX 170118</u>			
3303	(N81883)	TG-JAB	<u>WO 080312</u>	
3304	N37SA	VH-UOJ	<u>WO 140788</u>	
3305	N38SA	N41JH	N828FJ	
	N106FL	N106FW		
3306	N39SA	N10PP	CC-CGX	
	<u>MISSING AT SEA 180512</u>			
3307	N81SA	N200DR	<u>REGN EXPD, CNX 100914</u>	
3308	ZP-TMO	N7ZU	N621TJ	
3309	(N82SA)	N81885	VH-PCM	
	VH-PGM	N81885		

Sheet1

3310	N83SA	TG-IGN	TG-IGM	
	<u>DUMPED BY 0906</u>			
3311	N84SA	VH-PAR	(VH-YJK)	
	VH-UJR			
3312	(N82857)	(HR-MCT)	N82857	
	N540MT	N32GL		
3313	N89SA	N303EG	N233WM	CNX 220318, REST 300719
3314	N95SA	CC-CFL	<u>DITCHED 061188</u>	
3315	(N108SA)	N81891	VH-FGS	
	VH-YJS			
3316	N82855	VH-TLW	<u>CNX 130619</u>	
3317	(N8285A)	(N82862)	YV-219CP	
	YV-793P	J8-VBH	N14HR	
	N503AP	C6-CIP	N62WE	
3318	(N82863)	HR-MCT	FAH-008	
	<u>WFU</u>			
3319	(N109SA)	(N12RS)	N82864	
	N600CB	N49AC	PT-LGP	
	<u>N929JM REGN EXPD, CNX 090919</u>			
3320	N82869	N348TT	CC-CFU	
3321	(N82871)	6Y-JKC	N4196G	
	N602LP	N812TL	N9QY	
3322	(N82872)	LV-PDY	LV-OAT	
	N42ZZ			
3323	(N82877)	N12RS	VH-LTP	

MANUFACTURER'S NAME

Rockwell went through a number of name changes during the production of the Commander 500S, production being at Bethany (Wiley Post Airport), Oklahoma City, OK.

First 162 Aero Commander Division of North American Rockwell Corporation.

Next 44 Commander Aircraft Division, Rockwell International Corporation.

Last 110 General Aviation Division, Rockwell International Corporation.

First 162 49 in range c/ns 1755 to 1876, 3050 to 3162

Next 44 c/ns 3163 to 3206

Last 110 c/ns 3207 to 3323

PRODUCTION YEARS

From May 1968 to October 1979

NUMBERS CERTIFIED BY YEAR

1968	30
1969	46
1970	19
1971	17
1972	29
1973	33
1974	50
1975	45
1976	15
1977	12

Sheet1

1978	15
1979	5

Credits

My thanks go to Ton Van Soest for access to his AB files, supported by the research done by Barry Collman.

The above information on manufacturer's name changes and production years are taken from www.flightlevelsonline.com

Amendments and additions

As usual, these should be sent to me at les_hitchings@hotmail.com

Les Hitchings

13/03/22